

Q193 7333-240

Lot 526 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$61.00

Greenhaven #3

TYPE BUILDINGS

| | | |
|----------------------|---|-----|
| PERMIT NO. F-2630 | LOCATION 11 - Parklite Circle | A-3 |
| DATE Dec 20-65 | PURPOSE Const. dwlg. & att. gar. & cov. patio | |
| | OWNER Lee Basford 6600-Havenside Drive. | |
| ZONE R-1 | ARCH'T | |
| | CONT'R Owner same 422-0972 | |

| | | | | |
|---------------|---------|-------|-------|-------------------------------|
| VAL \$17,800. | STORIES | ROOMS | APTS. | 648 gar. SIZE 1800 sq. ft. |
|---------------|---------|-------|-------|-------------------------------|

| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|------------|----------|------------|-----------------|---------------|
| FORM | 12-25-65 | Callaway | | |
| JOIST | 1-17-66 | Perlo | | |
| FRAME | 2-14-66 | Caust | | |
| SHEET ROCK | 3-9-66 | Caust | | |
| FINAL | 4-29-66 | Perlo | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 1.12.66 | <i>Pl. Dist - No steel in suspension</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR