

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4313</i>	LOCATION <i>1025-9th Street</i>				
DATE <i>5/16/36</i>	PURPOSE <i>Modernizing old Bldg.</i>				
ZONE <i>Gen. Com.</i>	OWNER <i>Odd Fellows Temple Assoc.</i>				
	ARCH'T. <i>Chas. Dean Co. of Life Bldg.</i>				
	CONTR. <i>Wm. Ladue</i>				
VAL. <i>49,000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE	
LIGHT SHAFTS			ELEVATOR SHAFTS		
VENT SHAFTS			BOILER ROOMS		
OWNER'S INSPECTOR			SPRINKLER SYSTEM		
LATH			GAS VENTS		
FIRE ESCAPES			CHIMNEYS		
STAND PIPES			SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
1/22/05	Made frame just for attraction on 2 nd fl.
	No paint plaster ok. H. Campbell
	Also watched plastering.
	Attractions under the Porch complete ok
2/25/05	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. <i>Allen Campbell</i> INSPECTOR </div>