

Q 180 7480-489 49⁰⁰

Lot 346		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD				\$46.00
Glenbrook #4		TYPE BUILDINGS		Q 211 7129		
PERMIT NO. F-6550		LOCATION 8538 - Merribrook Drive				A-1
DATE Feb 28-67		PURPOSE Const. dwlg. & att. gar. Plan 403 LA				
ZONE R-1		OWNER Barbrook, Inc. 2777-Alvarado St., San Leandro				
		ARCH'T				
		CONT'R Besco same 363-7315				
VAL. \$12,400.		STORIES	ROOMS	APTS.	494-gar. SIZE 1230 sq. ft.	
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)	
FORM	4-17-67	Berlitz				
JOIST	5-10-67	Berlitz				
FRAME	5-25-67	Const. partial		6-7-67	Const	
SHEET ROCK	6-7-67	Const				
FINAL	7-2-67	Berlitz				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-2-67	Ok membrane Court
5-33-67	Pt frame - fireplace not finished Court
6-3-67	Pt SR - Lacked Court
6-6-67	Pt frame - fireplace has not finished Court
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div>