

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
615-Lelandhaven Way		3		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot 886 Greenhaven Unit No. 6					
TITLE AND NAME		ADDRESS		DATE	
Frank Schiro		16 Sail Ct.		6/30/71	
GEN. CONTR.		CITY LIC. NO.		DATE	
ELEC. CONTR.		422-7220		ELECTRICAL BY	
PLBG. CONTR.				PLUMBING BY	
MECH. CONTR.				MECHANICAL BY	
ARCH. ENGR.				DATE	
OWNER		555 Capitol Mall		CERTIFICATE OF OCCUPANCY	
Mike Gessford				ISSUED BY	
SIDE YARDS		REAR YARDS		DATE	
BLDG. WIDTH		BLDG. LENGTH		DATE	
TOTAL HEIGHT		NO. OF STORIES		DATE	
ROOF CONSTR.		AREA 1st FLOOR		DATE	
TOTAL AREA		C.S.D.		DATE	
480-garage 2,295 sq. ft.		C.I. CASE		DATE	
EXISTING BLDG'S SAME LOT		HOW USED		DATE	
SPACES		TREES RMVD.		DATE	
PARK'G REQ.		EXISTING BLDG'S SAME LOT		DATE	
USE ZONE		EXISTING BLDG'S SAME LOT		DATE	
SET BACK REQ.		EXISTING BLDG'S SAME LOT		DATE	
REAR YARDS		EXISTING BLDG'S SAME LOT		DATE	

NATURE OF WORK:- Const. dwlg. & attached garage

PERMIT NO. S.P. - H-721		ISSUED BY	
MICROFILM RECORD		MICROFILM RECORD	
ISSUANCE DATE		ISSUANCE DATE	
3/18/71		3/18/71	
VALUATION		VALUATION	
\$ 33,600.00		\$ 33,600.00	
R.U.F. FEE		R.U.F. FEE	
\$		\$	
S.M.I. FEE		S.M.I. FEE	
\$		\$	
PLAN CK. FEE		PLAN CK. FEE	
\$		\$	
SEWER INCL. FEE		SEWER INCL. FEE	
\$		\$	
PERMIT FEE		PERMIT FEE	
\$ 111.50		\$ 111.50	
TOTAL FEES		TOTAL FEES	
\$		\$	
REMARKS AND/OR VARIANCES		REMARKS AND/OR VARIANCES	
DWEILING		DWEILING	
521H40 - Frank		521H40 - Frank	
JOB FILE		JOB FILE	
REEL NO. 298		REEL NO. 298	
FRAME NO. 529		FRAME NO. 529	
TO 538		TO 538	
INSPECTION RECORD		INSPECTION RECORD	
REEL NO. 298		REEL NO. 298	
FRAME NO. 529		FRAME NO. 529	
TO 538		TO 538	
PLANS AND APPLICATION		PLANS AND APPLICATION	
REEL NO. 298		REEL NO. 298	
FRAME NO. 529		FRAME NO. 529	
TO 538		TO 538	
INSPECTION RECORD		INSPECTION RECORD	
REEL NO. 298		REEL NO. 298	
FRAME NO. 529		FRAME NO. 529	
TO 538		TO 538	
PLANS AND APPLICATION		PLANS AND APPLICATION	
REEL NO. 298		REEL NO. 298	
FRAME NO. 529		FRAME NO. 529	
TO 538		TO 538	
INSPECTION RECORD		INSPECTION RECORD	
REEL NO. 298		REEL NO. 298	
FRAME NO. 529		FRAME NO. 529	
TO 538		TO 538	