

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>Michy</i>	LOCATION <i>1740 Landon Ave. No. 17</i>		
DATE <i>9/11/30</i>	PURPOSE <i>Repair</i>	ROOMS	APTS.
ZONE	OWNER <i>Owen Stanley</i>	PHONE	
	ARCH'T		
	CONT'R <i>Stanley</i>		
	VAL. <i>95-</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			Cement Tests
Ex Wall	Joists						Chimneys		
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
9/8/30	Re-Roofing of Dids with Composition Shingles Completed O.K. Alder W Campbell
9/8/30	COMPLETED AND O.K. Alder W Campbell INSPECTOR