

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>A-5194</b>	LOCATION <b>1177 - Racine Way</b>			
DATE <b>11/6/36</b>	PURPOSE <b>New double garage</b>			
ZONE <b>2-Fam.</b>	OWNER <b>Mr. &amp; Mrs. Leslie McPeckold</b>			
	ARCH'T.			
	CONTR. <b>Stuckert &amp; Sons</b>			
VAL. <b>6500<sup>00</sup></b>	STORIES <b>1</b>	ROOMS <b>7</b>	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	<b>Area</b>
VENT SHAFTS		BOILER ROOMS	<b>1550<sup>01</sup></b>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<b>@ 350</b>
LATH		GAS VENTS*	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
11/9/36	1 <sup>ST</sup> /NSP. Forme. for Adote Res + baray. o.k. AW Campbell
1/5/37	2 <sup>ND</sup> /NSP. Frame o.k. AW Campbell
	<div data-bbox="319 896 470 940" data-label="Text">COMPLETE AND O. K.</div> <div data-bbox="1276 912 1436 940" data-label="Text">INSPECTOR</div>