

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 13-5916	LOCATION 574 - 5 th Street			
DATE 7/3/40	PURPOSE Re roof & Asbestos siding			
ZONE	OWNER Juanita Fernandez			
	ARCH'T.			
	CONTR. Walsh Roofing Co.			
VAL. 4000	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
7/5/20	1 st / HSP. Inspected Present Foundation for Drilling to be prepared for flat below. ^{OK} All Completed.
7/29/20	2 nd / HSP. Part Frame for 1 st Floor Ties. All Completed.
8/9/20	2 nd / HSP. Bal of Frame ^{OK} All Completed.
	3 rd / HSP. Going to use Sheet Piles for Wall & Cutting of flat below.

COMPLETE
AND O. K.

INSPECTOR