

K487217

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

| | | | | | |
|-------------|----------|-----------------------|-----------------|---------------------------------|------------|
| PERMIT NO. | | LOCATION | | A-1 | |
| E-998 | | 107 - San Antonio Way | | | |
| DATE | | PURPOSE | | Const. detached private garage. | |
| Apr. 6-62 | | OWNER | | Clinton Schiveley Same | |
| ZONE | | ARCH'T | | | |
| R-1 | | CONT'R | | Owner GL 7-6843 | |
| VAL. \$900. | | STORIES | ROOMS | APTS. | SIZE |
| | | 1 | | | 360 sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | | |
| FORM | 1-2-63 | Build | | | |
| JOIST | | | | | |
| FRAME | 1-7-63 | Build | | | |
| SHEET ROCK | 1-9-63 | Build | | | |
| FINAL | 10-19-64 | Per | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 8.13.62 | PK frame. <i>Back to</i> Use one frame |
| 4.14.63 | Checked progress <i>Rec'd</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |