

Q 191 F 271-276

| | | | | | |
|----------------------|----------|--|-----------------|---------------|------------|
| Lot 364 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$55.00 |
| Glenbrook #4 | | TYPE BUILDINGS | | | Q 217 F 34 |
| PERMIT NO. F-7350 | LOCATION | 2801 - Sarina Court | | A-1 | |
| DATE May 17-67 | PURPOSE | Const. dwlg. & att. gar. Plan 604 LA | | | |
| | OWNER | Center Devl 2777-Alvarado St., | | | |
| ZONE R-1 | ARCH'T | San Leandro | | | |
| | CONTR | Besco same 363-7315 | | | |
| VAL. \$15,600. | STORIES | ROOMS | APTS. | 446-gar. | SIZE |
| | | | | 1593 sq. ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 5-29-67 | Field | | | |
| JOIST | 6-30-67 | Joist | | | |
| FRAME | | Wallway | | | |
| SHEET ROCK | 9-1-67 | Wallway | | | |
| FINAL | 10-13-67 | ABG | | | |

11
10
9
8
7
6
5
4
3
2
1

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------|--|
| 6-2-67 | Plc membrane <i>Paul</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |