

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS *Riverside Valley Way 3rd & 4th Ave*

PERMIT NO. 8073	LOCATION <i>Lot #46 Swanston Park Unit #2. 1132-3⁰⁰ Ave</i>
DATE <i>MAY 25th 1931.</i>	PURPOSE <i>Build 1 1/2 Story Family Brick-Veneer 7' Pan Only 1 Garage.</i>
ZONE <i>2-Family</i>	OWNER <i>C. C. RUBY, 4800 T. ST</i>
	ARCH'T
	CONT-R <i>OWNER</i>

VAL. <i>6300⁰⁰</i>	STORIES <i>1 1/2</i>	ROOMS <i>7</i>	APTS. <i>1</i>	SIZE <i>36 x 42'</i>
-------------------------------	----------------------	----------------	----------------	----------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
5/26-31	1 st Insp Form OK P H Rutter
6/10-31	2 " Frame " P H Rutter
6/18-31	3 " Int Lock " P H Rutter
7/21/31	4 th Insp. Dwg & Garage Completed A W Campbell
7/21/31	ISSUED CERTIFICATE OF OCCUPANCY *8873
7/21/31	Street Cleaned up OK A W Campbell
7/21/31	COMPLETE AND O.K. <i>Address to Inspector</i> INSPECTOR