

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA		FINAL INSPECTIONS	
		3066 Bridgeford Drive				A-6			
LEGAL DESCRIPTION					OCCUP. GR.	CONST. TYPE	VAR. NO.	FIRE ZONE	
Larchmont Northgate #2 Lot 139									BUILDING BY Riolo
TITLE AND NAME		1/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Owner									12-9-70
ELEC. CONTR.								PLUMBING BY	DATE
PLBG. CONTR.								MECHANICAL BY	DATE
MECH. CONTR.									
ARCH. ENGR.									
OWNER Larchmont Northgate								CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
						305 GAR 994 sq ft		CENSUS TRCT. NO.	
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED
			R-1						

NATURE OF WORK:- Const. dwelling and garage

PERMIT NO. S.P. G-7617	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 285	FRAME NO:- 385	TO
ISSUANCE DATE Jul 22-70	INSPECTION RECORD	REEL NO. 410	FRAME NO 595	R267 F160-167 Plans
VALUATION \$ 15,000	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$				
S.M.I. FEE \$				
PLAN C.K. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$	REMARKS AND/OR VARIANCES			
\$	Form: 8-14-'70 Riolo			
\$	Frame: 9-14-'70 Riolo			
TOTAL FEES \$ 59	Riolo : Sheet Rock 9-22-'70			

