

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-5290</i>	LOCATION <i>2724 - 13<sup>th</sup> St</i>			
DATE <i>11/24/36</i>	PURPOSE <i>Erect new double garage</i>			
ZONE	OWNER <i>Sisterio Martinelli</i>			
	ARCH'T.			
	CONTR. <i>N. Martinelli 3168 - Riverside</i>			
VAL. <i>5000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS <i>0</i>			
VENT SHAFTS	BOILER ROOMS <i>1540<sup>01</sup></i>			
OWNER'S INSPECTOR	SPRINKLER SYSTEM <i>@ 350</i>			
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK-REMARKS
11/25/36	1 <sup>ST</sup> / N.S.P. Frames in place <sup>OK</sup> A.W. Campbell
12/15/36	2 <sup>ND</sup> / N.S.P. Frames . . . . <sup>OK</sup> A.W. Campbell
12/14/36	3 <sup>RD</sup> / N.S.P. EXT. LATK . . . . <sup>OK</sup> A.W. Campbell
12/18/36	3 <sup>RD</sup> / N.S.P. INT. LATK . . . . <sup>OK</sup> A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="305 823 427 859">COMPLETE AND O. K.</span> <span data-bbox="1117 839 1246 859">INSPECTOR</span> </div>