

R222 F403

Lot 393		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$49.00
Southgate Meadows #6		TYPE BUILDINGS		R212 F518-525	
PERMIT NO.					
F-8196	LOCATION	7721 Quinby Way			A-5
DATE	PURPOSE	Const. dwelling & garage 100 L			
Aug. 11/67	OWNER	Valbrook 2777 Alvarado St., San Leandro			
ZONE	ARCH'T				
R-1	CONTR	Besco 2777 Alvarado St., San Leandro			
VAL. \$13,900.	STORIES	ROOMS	APTS.	456 gar. SIZE	
	1	5		1,383 sq. ft.	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
				383-9315	
FORM	4-5-67 Larson				
JOIST	9-10-67 Court				
FRAME	10-19-67 Larson				
SHEET ROCK	11-24-67 Larson				
FINAL	1-10-68 [Signature]				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
9-1-67	Pt Form. Paste grade beam
	not formed correct Larson
9-14-67	MC membrane Larson
10-17-67	Pt Forme - not ready Larson
10-18-67	Pt Exam - Day incomplete. Clark
	formwork. nail jacking Larson
1-8-68	Pt Final - occupied Court
COMPLETE AND OK	INSPECTOR