

R222 F403

| | | | | | |
|----------------------|---------------------|--|-----------------|---------------|---------------|
| Lot 393 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$49.00 |
| Southgate Meadows #6 | | TYPE BUILDINGS | | | R212 F518-525 |
| PERMIT NO. | | | | | |
| F-8196 | LOCATION | 7721 Quinby Way | | A-5 | |
| DATE | PURPOSE | Const. dwelling & garage 100 L | | | |
| Aug. 11/67 | OWNER | Valbrook 2777 Alvarado St., San Leandro | | | |
| ZONE | ARCH'T | | | | |
| R-1 | CONTR | Besco 2777 Alvarado St., San Leandro | | | |
| VAL. \$13,900. | STORIES | ROOMS | APTS. | 456 gar. SIZE | |
| | 1 | 5 | | 1,383 sq. ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| | | | | 383-9315 | |
| FORM | 4-5-67 Larson | | | | |
| JOIST | 9-10-67 Court | | | | |
| FRAME | 10-19-67 Larson | | | | |
| SHEET ROCK | 11-24-67 Larson | | | | |
| FINAL | 1-10-68 [Signature] | | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| 9-1-67 | Pt Form. Paste grade beam |
| | not formed correct Larson |
| 9-14-67 | MC membrane Larson |
| 10-17-67 | Pt Forme - not ready Larson |
| 10-18-67 | Pt Exam - Day incomplete. Clark |
| | formwork. Nail jacking Larson |
| 1-8-68 | Pt Final - occupied Court |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |