

*R-227 F-235*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$6.00**
**TYPE BUILDINGS**

PERMIT NO. <b>H-6499</b>		LOCATION <b>360 - Morey Avenue</b> <b>A-6</b>			
DATE <b>Apr. 26-72</b>		PURPOSE <b>Make repairs to front entrance of</b>			
ZONE		OWNER <b>Church of Christ</b> <b>Same /church bldg.</b>			
		ARCH'T			
		CONTR <b>Owner</b> <b>Same</b> <b>662 8770</b>			
VAL. <b>\$200.</b>		STORIES <b>1</b>	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	<i>5-4-72</i>	<i>Chapin</i>	<b>B-3</b>		
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>5-18-72</i>	<i>Chapin</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR