

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B 9433</b>	LOCATION <b>5300 - 5 St.</b>
DATE <b>10/24/41</b>	PURPOSE <b>Erect new dwg + gar</b>
ZONE <b>—</b>	OWNER <b>Phillip L. Ott</b>
	ARCH'T. <b>—</b>
	CONTR. <b>Owner</b>

VAL <b>3000</b>	STORIES <b>—</b>	ROOMS <b>5</b>	APTS.	SIZE
--------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<b>950° @ 3" =</b>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS	
11/21/41	1 <sup>5</sup> In p	Forms OK <i>P</i>
4-1-42	2 "	Frame OK <i>P</i>
4/20/42	3 "	Sph. Set OK <i>P</i>

COMPLETE  
AND O. K.

INSPECTOR