

## RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
10/14/26	B. \$ 319.00	4214	Repair garage damage by fire-Dwlg	Geo Barr 2672 Montgomery Way	Paul R. Opdyke 3239 E. St.		
3/25/31	B. \$ 1000	7825	Add 1 rm & sleeping porch-Dwlg	Mariland	Truesdale		
5/3/65	B. \$ 600.00	F-405 \$ 10.00	Repair termite damage to dwg & ded. gar.	Mr. E. D. Nicholaus Same	Ketley's Research Lab Gallo 3376 Fulton Ave.		6/23/66
10/31/67	B. \$ 400.00	F-8912 \$ 5.00	Repair termite damage to dwlg	Haywood Same	Paramount Pest Con. 6405 Elvas Ave.	Chapin	1/17/68
11/24/76	E. \$ 200.00	D-9293 \$ 20.00 G-9065	House-Update servive entrance & new serive Dwlg	Connie Carey Same	Owner Same	Clark	4/25/77 E
1/31/77	B.P.E. \$ 10,000.00	E-643 \$ 127.00 G-9064	Fire Damage Repair	Connie Carey Same	Petersen & Associates 1800 27th St.	Riplo, Clark Dizoreto	4/25/77 B 4/25/77 E 4/28/77 PM

## MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
4214	R 464 F 029 - Comb	E-643	R 480 F 502		
7825	R 464 F 029 - 690-Comb				
F-405	R167 F347				
F-405	R 464 F 029 - Comb				
F-8912	R227 F528				
F-8912	R 464 F 029 - Comb				
D-9293	R 464 F 029				
E-643	R 479 F 572				
D-9293	R 480 F 502				

