

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
382-DuBois Ave.		382-DuBois Ave.		6	
LEGAL DESCRIPTION					
Lot 219 Glenwood Park #1					
TITLE AND NAME					
1/c Owner					
GEN. CONTR.					
Owner					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
David E. Bohannon					
5888 Hillisdale Blvd.					
CERTIFICATE OF OCCUPANCY					
CONST. LOAN LENDER					
BLDG. WIDTH					
BLDG. LENGTH					
TOTAL HEIGHT					
NO. OF STORIES					
ROOF CONSTR.					
AREA 1st FLOOR					
TOTAL AREA					
C.S.D.					
C.I. CASE					
BLDG. LENGTH					
REAR YARDS					
SET BACK REQ.					
USE ZONE					
1					
PARK'G REQ.					
SPACES					
TREES RMVD.					
EXISTING BLDG'S SAME LOT					
HOW USED					

NATURE OF WORK:- Construct dwelling & garage MF#11-B-1					
PERMIT NO. S.P. H-4216					
ISSUED BY					
MICROFILM RECORD					
PLANS AND APPLICATION					
REEL NO. 315		FRAME NO. 121		TO 130	
INSPECTION RECORD					
REEL NO.		FRAME NO.		TO	
JOB FILE					
R.U.F. FEE					
\$ 19,900.00					
VALUATION					
ISSUANCE DATE					
11/9/71					
\$ 28.00					
PERMIT FEE					
\$ 28.00					
SEWER INCL. FEE					
\$					
PLAN CK. FEE					
\$					
S.M.I. FEE					
\$					
PLAN CK. FEE					
\$					
SEWER INCL. FEE					
\$					
TOTAL FEES					
\$					
REMARKS AND/OR VARIANCES					
1086 052 DWELLING					
R*96F084 - final					