

R-71

|                      |   |   |       |      |  |
|----------------------|---|---|-------|------|--|
| Lot 143              |   | BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD 1-367- |       |      |  |
| W. & K. Tct. #43     |   | <b>TYPE BUILDINGS \$3.00</b>                              |       |      |  |
| PERMIT NO.<br>D-6019 | LOCATION<br>590 Pala Way                      | A-1   |       |      |  |
| DATE<br>Jun. 20, 60  | PURPOSE Remodel existing 2nd floor room dwlg. |   |       |      |  |
| ZONE<br>R-1          | OWNER Ernest S. Naschke                       |   |       |      |  |
|                      | ARCH'T  |   |       |      |  |
|                      | CONTR' owner GL 6-1938                        |   |       |      |  |
| VAL. \$300.          | STORIES                                       | ROOMS   | APTS. | SIZE |  |
| INSP.                | DATE  | INSPECTOR   |       |      |  |
| FORM                 | 6-30-60                                       | <i>Jones</i>  |       |      |  |
| JOIST                | 6-30-60                                       | <i>Jones</i>  |       |      |  |
| FRAME                | 6   |   |       |      |  |
| LATH                 |   |   |       |      |  |
| FINAL                |   |   |       |      |  |

| DATE            | SPECIAL CONDITIONS OF WORK—REMARKS            |
|-----------------|---|
| <i>10-20-60</i> | <i>No inspection - still working - locate</i> |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 | <b>COMPLETE<br/>AND OK</b>                    |

**INSPECTOR**