

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-7615</i>	LOCATION <i>1022-5th Street</i>			
DATE <i>12/22/37</i>	PURPOSE <i>Remodel for restaurant</i>			
ZONE	OWNER <i>Kindelberg</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>2002</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS			
VENT SHAFTS	BOILER ROOMS			
OWNER'S INSPECTOR	SPRINKLER SYSTEM			
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS
12/23/37	2 ND HSP. Frame for Bortles + Ben Jan for Return road O.K. M. Campbell
	<p data-bbox="319 837 445 878">COMPLETE AND O. K.</p> <p data-bbox="1166 852 1299 873">INSPECTOR</p>