

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>2915</i>	LOCATION <i>2616 San Francisco</i>		
	PURPOSE <i>add Pkwt.</i>	ROOMS	APPTS.
DATE <i>2-1928</i>	OWNER <i>Mc Miller</i>		PHONE
ZONE <i>2</i>	ARCHT <i>Over</i>		
2-1928	CONTR <i>Over</i>		
VAL. <i>200 -</i>	STORIES	SIZE	

SACRAMENTO BUILDING DIVISION

FOUNDATION	STORY	BSMT	1	2	3	ROOF	Chimneys		Cement Tests
Ex Wall	Joists								
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE

CONDITION OF WORK—REMARKS

7/9/28

2<sup>nd</sup> flr/1<sup>st</sup> flr. Frame. Owner changed plans at present. I  
Decided set & ceiling room in front. Inst. installed a  
large window in front room. Inspected walls  
at side of house. same O.K. according to street grade.  
House originally built near ass. to line and before  
street was paved.

A. J. Campbell

COMPLETED  
AND O. K.

INSPECTOR