

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1742</i>	LOCATION <i>4740 - 2nd Ave</i>			
DATE <i>10/14/38</i>	PURPOSE <i>General repair to dwg</i>			
ZONE	OWNER <i>Julia W. Mahon</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS	
12-25-38	1	Lump Formed on Roof
12-23-38	2	" Framing " Roof
1-4-39	3	" Lath Int " Roof
	COMPLETE AND O. K.	
	INSPECTOR	