

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,716</i>	LOCATION <i>365 - Santa Ynez Way</i>			
DATE <i>9/22/42</i>	PURPOSE <i>Rebuild garage due to fire</i>			
ZONE	OWNER <i>S. Beckner</i>			
	ARCH'T.			
	CONTR. <i>Chas Vanina</i>			
VAL. <i>494⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE.	CONDITION OF WORK—REMARKS
	<p data-bbox="344 853 468 893">COMPLETE AND O. K.</p> <p data-bbox="1161 868 1291 893">INSPECTOR</p>