

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-11973	LOCATION 1914 - 5th St
DATE 1/27/44	PURPOSE Dr. Repairs to dwg.
ZONE	OWNER A. Mendez
	ARCH'T.
	CONT'R. Chas. Varona

VAL. 65302	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/28/17	2 ND INSP. Frame for Repairs to rear of 2-Story Dwelling recently damaged by fire. O.K. R.W. Campbell
	COMPLETE AND O. K. INSPECTOR