

R 255 + 477

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

PERMIT NO.	LOCATION
G-2701	2766 - San Luis Court A-2 (22)
DATE	PURPOSE
Mar-7-69	Repair rot damage to dwelling
ZONE	OWNER
R-1	Lily Leong 2766 - San Luis Ct.
	ARCH'T
	422-8880
	CONT'R
	Midstate Termite Box 8827

VAL. \$500.	STORIES	ROOMS	APTS.	SIZE
-------------	---------	-------	-------	------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM				
JOIST				
FRAME				
SHEET ROCK				
FINAL				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK INSPECTOR