

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4184</i>	LOCATION <i>921 - Corona Way</i>
DATE <i>11/3/39</i>	PURPOSE <i>General Repair to dwlg. of</i>
ZONE	OWNER <i>Edwin Skollan</i>
	ARCH'T.
	CONT'R. <i>E. E. Sydenstricker</i>

VAL. <i>2500</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="349 850 474 888">COMPLETE AND O. K.</p> <p data-bbox="1177 871 1306 891">INSPECTOR</p>