

A 208, F 136

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD *\$Gratis*

## TYPE BUILDINGS

PERMIT NO.	LOCATION				811 - Union Street	A-6
W-2961	PURPOSE				Wreck 1-family dwelling	
DATE	OWNER				John Steely	5131-Sandburg Drive
Dec 21-66	ARCH'T					
ZONE	CONTR				Owner	Same 456-3440
VAL.	STORIES		ROOMS	APTS.	SIZE	
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)	
FORM						
JOIST						
FRAME						
SHEET						
ROCK						
FINAL	1-23-67	hallway			exit	

*Condensed Copy  
Community Improvement*

DATE

SPECIAL CONDITIONS OF WORK — REMARKS

COMPLETE  
AND OK

INSPECTOR