

R 293 F 52

| | | | | | |
|----------------|--------------------------------------|--|-----------------|---------------|---------------------|
| Lot #1121 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$83.00 |
| Glenbrook #11 | | TYPE BUILDINGS | | | R 299 F 71-80 PLANS |
| PERMIT NO. | G-9381 | | | | |
| LOCATION | 5 - Nob Court A-1 (52) | | | | |
| DATE | Dec. 11-70 | | | | |
| PURPOSE | Const. dwelling & att. garage MP#101 | | | | |
| OWNER | Edificios, Inc. 2777-Alvarado St. | | | | |
| ZONE | R-1 | | | | |
| ARCH'T | Besco Builders, Inc. San Leandro | | | | |
| CONTR | Besco Builders, Inc. San Leandro | | | | |
| VAL. \$23,000. | STORIES | ROOMS | APTS. | SIZE | |
| | 1 & 2 | | | 462-gar. | 1,525 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| | | | | 483-4300 | |
| FORM | 1-8-71 | <i>Revised</i> | | | |
| JOIST | | | | | |
| FRAME | 4-6-71 | <i>Revised</i> | | | |
| SHEET ROCK | 4-14-71 | <i>Revised</i> | | | |
| FINAL | 5-19-71 | <i>Revised</i> | | | |

11 Lines

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| 3-1-71 | OK Sub <i>Rolls</i> |
| 4-7-71 | Pt Crust - not ready <i>Rolls</i> |
| 5-18-71 | OK Tread - not ready <i>Rolls</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |