

E-338 F421-438

Lot 16		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$157.00
Blk 23, Map or Oak Park & South Sacto.		TYPE BUILDINGS			
PERMIT NO. H-9330	LOCATION 3123 - 2nd Avenue			A-4	
DATE Oct 30-72	PURPOSE	Const. 5-unit townhouse apt bldg.			
	OWNER	Dodd & Hollis 2710-X St.			
ZONE R-4	ARCH'T	J. C. Dodd			
	CONTR	Owners same 452-6411			
VAL. \$51,000.		STORIES 2	ROOMS	APTS.	SIZE 3935 sq. ft.
INSP.	DATE	BLDG. TYPE V- no hr.	OCCUPANCY GROUP H-1	PHONE (O) (C)	
FORM	1-5-73	Berkato	Certificate sent 1/22/74 J. S.		
JOIST					
FRAME	4-3-73	Hammora	Certificate sent 1-27-74 J. S.		
SHEET ROCK					
FINAL	1-16-74	J. S. Sera	J. S.		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-29-72	P.S. No plans, coord, address ^{Harmon} Harmon
1-2-73	1. four - steps. 7th day - steel not in place
1-26-73	med. pipe, not placed O.K. - slab - ^{Harmon} Harmon
2-15-73	O.K. sidewalk clear ^{Harmon} Harmon
3-6-73	P.S. Flaming. No plans on job ^{Harmon} Harmon
3-12-73	P.S. Log - saw no ladder ^{Harmon} Harmon
3-14-73	O.K. Roof nail - ^{Harmon} Harmon
4-19-73	O.K. Wall - ^{Harmon} Harmon
10-4-73	PT. - Find - ^{Sidewalk, steps packing} Roof damage ^{Harmon} Harmon
	COMPLETE AND OK INSPECTOR