

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-33725</i>	LOCATION <i>1938 - Stockton Blvd.</i>			
DATE <i>Oct 5-51</i>	PURPOSE <i>Remodel inter. bldg.</i>			
ZONE	OWNER <i>Dr. W. Kinkas</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>300</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="288 850 409 888">COMPLETE AND O. K.</p> <p data-bbox="1078 864 1205 884">INSPECTOR</p>