

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| | | | | | |
|--------------------------|--|--------------------------|--|-----------------|--|
| PROPERTY PARCEL NO. | | JOB ADDRESS | | INSPECTION AREA | |
| 3927 Belden St. | | 6 | | | |
| LEGAL DESCRIPTION | | | | | |
| Del Paso | | | | | |
| TITLE AND NAME | | ADDRESS | | ZIP | |
| Orman Haenggi | | 1615 Arcade Blvd. | | | |
| GEN. CONTR. | | CITY LIC. NO. | | TEL. NO. | |
| ELEC. CONTR. | | | | | |
| PLBG. CONTR. | | | | | |
| MECH. CONTR. | | | | | |
| ARCH. ENGR. | | | | | |
| OWNER | | CONST. LOAN LENDER | | | |
| J. R. Schmits | | 2707 Del Paso Blvd. | | | |
| CERTIFICATE OF OCCUPANCY | | ISSUED BY | | | |
| DATE | | DATE | | | |
| PLUMBING BY | | TOTAL AREA | | | |
| DATE | | C.S.D. | | C.I. CASE | |
| MECHANICAL BY | | EXISTING BLDG'S SAME LOT | | HOW USED | |
| DATE | | 924 | | | |
| | | SPACES | | TRES RMVD. | |
| | | PARK'G REQ. | | NO. OF STORES | |
| | | USE ZONE | | ROOF CONSTR. | |
| | | 1 | | AREA 1st FLOOR | |
| | | REAR YARDS | | TOTAL HEIGHT | |
| | | SET BACK REQ. | | BLDG. LENGTH | |
| | | SIDE YARDS | | TOTAL HEIGHT | |

NATURE OF WORK:- Const. dwelling & carport

| | | | |
|--------------------------|--|---|--|
| PERMIT NO. S.P. - R-6266 | | ISSUED BY | |
| 2-19-64 | | ISSUANCE DATE | |
| \$8,200.00 | | VALUATION | |
| \$ | | R.U.F. FEE | |
| \$ | | S.M.I. FEE | |
| \$ | | PLAN CK. FEE | |
| \$ | | SEWER INCL. FEE | |
| \$34.00 | | PERMIT FEE | |
| \$ | | TOTAL FEES | |
| MICROFILM RECORD | | REMARKS AND/OR VARIANCES | |
| Dwelling | | | |
| PLANS AND APPLICATION | | REEL NO. R-137 . FRAME NO. 356 TO 554 | |
| INSPECTION RECORD | | REEL NO. 21802 FRAME NO. 081 (overbore) | |
| JOB FILE | | REEL NO. TO | |