

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-2535</i>	LOCATION <i>231 - Q St -</i>			
DATE <i>2/21/35</i>	PURPOSE <i>Gen. Alterations Auto Rooms</i>			
ZONE <i>Gen Com</i>	OWNER <i>Mrs J. M. Peicheiro</i>			
	ARCH'T <i>Don Fathi</i>			
	CONT'R <i>Don Fathi</i>			
VAL. <i>5000</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
2/21/35	Repairs to Store Front & Interior damaged by Auto Accident. Frame Replaced ^{OK} A.W. Campbell
2/28/35	Also repairs to interior plaster ^{OK} A.W. Campbell
3/4/35	Repairs completed OK A.W. Campbell
3/4/35	COMPLETE AND O.K. <i>Alden H. Campbell</i> INSPECTOR