

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-4317</i>	LOCATION <i>1416 - 9th St.</i>			
DATE <i>5/15/36</i>	PURPOSE <i>Repair Brick Bldg. Comp.</i>			
ZONE	OWNER <i>Feldhusens Grocery Store</i>			
	ARCH'T.			
	CONTR. <i>Charles S. Owens Co.-4</i>			
VAL. <i>25000</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR	<i>Wrecked</i>	SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE

CONDITION OF WORK-REMARKS

5/22/36

Re Roofing of Fullhouse Store Bldg  
with built-up composition Roofing.  
Completed

*W. W. Campbell*

~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~

5/22/36

COMPLETE  
AND O. K.

*W. W. Campbell*

INSPECTOR