

R 284 E 112

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$Gratis

Expires Jul-26-70 TYPE BUILDINGS

| | |
|----------------------|--------------------------------------|
| PERMIT NO. W-5153 | LOCATION 5137 - Ada Lane A-7 (72.04) |
| DATE Jun-26-70 | PURPOSE Wreck 1-family dwelling |
| | OWNER Merle B & Violet D. Renslow |
| ZONE | ARCH'T |
| | CONT'R Owner 5111-Ada Lane 991-3538 |

| | | | | |
|------|---------|-------|-------|------|
| VAL. | STORIES | ROOMS | APTS. | SIZE |
|------|---------|-------|-------|------|

| | | | | |
|-------|------|------------|-----------------|---------------|
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|-------|------|------------|-----------------|---------------|

| | | | | |
|------|--|--|--|--|
| FORM | | | | |
|------|--|--|--|--|

| | | | | |
|-------|--|----------------------------------|--|--|
| JOIST | | (Condemned by Community Housing) | | |
|-------|--|----------------------------------|--|--|

| | | | | |
|-------|--|--|--|--|
| FRAME | | | | |
|-------|--|--|--|--|

| | | | | |
|------------|--|--|--|--|
| SHEET ROCK | | | | |
|------------|--|--|--|--|

| | | | | |
|-------|--|--|--|--|
| FINAL | | | | |
|-------|--|--|--|--|

*1st inspection
7-21-70 P.C.
Final inspection
7-28-70 J.V.B.
ent*

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| 7-20-70 | Down lot not clear - pink pass |
| | partly - sink - basin Chassis |
| 7-27-70 | In a mess |
| | Sawto |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |