

240 7779-7824

Lot #13

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$38.50

S.L.P.H. Mañor#

TYPE BUILDINGS

PERMIT NO. D-9982	LOCATION 4746 - Norm Circle		A-3	
DATE Nov 1-61	PURPOSE Erect dwelling & attached garage			
ZONE R-1	OWNER Woodard & Assoc. 4115 1/2 - Franklin Blvd.			
	ARCH'T			
	CONT'R Cwner Same		GL 1-9657	
VAL. \$14,000	STORIES 1	ROOMS 6	APTS. 500 gar.	SIZE 1423 sq. ft.
INSP.	DATE	INSPECTOR		
FORM	11-6-61	Borlato		
JOIST	11-9-61	Borlato		
FRAME	12-7-61	Borlato		
LATH	12-6-61	Fulley		
FINAL	5-14-62	R. J. [Signature]		

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
11-3-61	P.T. No mudsill on job. Barbed PT frame: For wall. Mudsill. Cap in
11-29-61	wrong place. Mudsill in window. Not level Roof
12-1-61	Blocking out of the ceiling & other frames. Clearing traces, gable end of garage. Installation of furnace, etc.
4-4-62	Solid, work to inspect. Curt
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div>