

J  
BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-37792</b>	LOCATION <u>4047 Miller Way</u>			
DATE <b>4-14-53</b>	PURPOSE <u>Erect duplex and attached pri. double garage.</u>			
ZONE	OWNER <u>Charles W. Phillips</u>			
	ARCH'T.			
	CONTR. <u>Charles W. Phillips</u>			
VAL. <b>\$17,730.00</b>	STORIES	ROOMS	APTS.	SIZE
<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>		
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>		
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>		
<b>LATH</b>		<b>GAS VENTS</b>		
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>		
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>		

DATE	CONDITION OF WORK—REMARKS	
4-17-5	Fence	M.D. Sherrington
5-28-53	Frame	M.D.
7-		
		<p data-bbox="279 832 408 871"><b>COMPLETE AND O. K.</b></p> <p data-bbox="1136 850 1270 871"><b>INSPECTOR</b></p>