

|               |           |  |                                      |       |               |
|---------------|-----------|--|--------------------------------------|-------|---------------|
| Lot #894      |           | BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD |                                      |       | \$31.00       |
| Northgate #6  |           | TYPE BUILDINGS                                     |                                      |       |               |
| PERMIT NO.    | D-9818    | LOCATION   | 1206 - West El Camino Ave. A-2       |       |               |
| DATE          | Oct 13-61 | PURPOSE  | Erect dlwg. & att. gar. Plan #700    |       |               |
| ZONE          | R-1       | OWNER  | DuBrow-Pleman Bldrs. 2601 - Erin Dr. |       |               |
|               |           | ARCH'T   |                                      |       |               |
|               |           | CONT'R   | Owner                                | Same  | WA 2-6897     |
| VAL. \$10,600 |           | STORIES  | 1                                    | ROOMS | 528 gar. SIZE |
|               |           |  |                                      | APTS. | 1042 sq. ft.  |
| INSP.         | DATE      | INSPECTOR  |                                      |       |               |
| FORM          | 10-26-61  | Fuller   |                                      |       |               |
| JOIST         |           |  |                                      |       |               |
| FRAME         | 12-22-61  | Fuller   |                                      |       |               |
| LATH          | 1-8-62    | Burbato  |                                      |       |               |
| FINAL         | 4-24-62   | Burbato  |                                      |       |               |

| DATE   | SPECIAL CONDITIONS OF WORK—REMARKS                              |
|--------|---|
| 1.3.62 | P4DR Edges not nailed Jones                                     |
| 1.5.62 | P4DR P4DR not nailed at top joints & corners <sup>to slab</sup> |
| 1.8.62 | Kitchen window for small Bedst                                  |
|        |   |
|        |   |
|        |   |
|        |   |
|        |   |
|        |   |

COMPLETE  
AND OK

INSPECTOR