

L232 F384

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$Gratis

## TYPE BUILDINGS

254 F618-619 file

|                      |          |                                     |                 |  |
|----------------------|----------|-------------------------------------|-----------------|--|
| PERMIT NO.<br>W-3590 | LOCATION | 2221 - 5th Street A-2 (21)          |                 |  |
| DATE<br>2/2/68       | PURPOSE  | Wreck 1-unit office                 |                 |  |
| ZONE                 | OWNER    | Shell Oil Co. 2545 Fair Oaks Blvd.  |                 |  |
|                      | ARCH'T   |                                     |                 |  |
|                      | CONT'R   | Roy Nielsen Rt. 2 Box 4101 363-0290 |                 |  |
| VAL.                 |          | STORIES                             | ROOMS           | APTS. SIZE   |
| INSP.                | DATE     | BLDG. TYPE                          | OCCUPANCY GROUP | PHONE (O) (C)                                      |
| FORM                 |          |                                     |                 |  |
| JOIST                |          |                                     |                 |  |
| FRAME                |          |                                     |                 |  |
| SHEET ROCK           |          |                                     |                 |  |
| FINAL                | 5-9-68   | Hammuna                             |                 | <i>extended</i><br><i>3.5.68 off</i><br><i>Eng</i> |

| DATE    | SPECIAL CONDITIONS OF WORK — REMARKS                               |
|---------|--|
| 3-4-68  | Set up lines and other hardware                                    |
| 4-24-68 | letter given to city att: CH-                                      |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |