

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-9314</i>	LOCATION <i>1315-Manson Way</i>
DATE <i>10/10/41</i>	PURPOSE <i>First floor dwlg. & gar.</i>
ZONE <u> </u>	OWNER <i>Dave Hall</i>
	ARCH'T. <u> </u>
	CONTR. <i>Owner</i>

VAL. <i>5850⁰⁰</i>	STORIES <u> </u>	ROOMS <i>4</i>	APTS.	SIZE
-------------------------------	----------------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>1268^{sq} ft</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3^{1/2}</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
9/16/41	1 ST /NSP. Forms in place ^{OK} A.W. Campbell
10/29/41	2 ND /NSP. Frame ^{OK} A.W. Campbell
11/5/41	3 RD /NSP INT & EXT LATH ^{OK} A.W. Campbell
12/20/41	4 TH /NSP! Drying & Garage Completed ^{OK}
12/20/41	<p>COMPLETE AND O. K. <i>Allen W Campbell</i> INSPECTOR</p>