

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>8596</b>	LOCATION <b>919 MISSION WAY</b>			
DATE <b>Sept 17 1931</b>	PURPOSE <b>Make general Repairs and paint Ext. of Dwlg.</b>	PHONES		
ZONE <b>2-Family</b>	OWNER <b>MRS. E. I. PATTERSON.</b>	ARCHT		
	CONT-R <b>CARL VOGT. 3332 Truckee Way.</b>			
VAL. <b>250<sup>00</sup></b>	STORIES	ROOMS	APTS.	SIZE
Light Shafts			Elevator Shafts	
Vent Shafts			Boller Rooms	
Owner's Inspector			Sprinkler System	
Lath			Gas Vents	
Fire Escapes			Chimneys	
Stand Pipes			Skylights	

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="306 826 458 878">COMPLETE AND O.K.</p> <p data-bbox="1094 847 1251 871">INSPECTOR</p>