

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>4330-A</i>	LOCATION <i>3681 East Lincoln Ave.</i>			
DATE <i>5/19/36</i>	PURPOSE <i>Erect new residence</i>			
ZONE <i>One Fam.</i>	OWNER <i>Mr. & Mrs. Vernon Hansen</i>			
	ARCH'T. <i>Holderen Const. Co.</i>			
VAL. <i>8000⁰⁰</i>	STORIES <i>2</i>	ROOMS <i>7</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 2096⁰</i>	
VENT SHAFTS		BOILER ROOMS	<i>@ 350</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
9-14-37	1 st Insp. Frame OK <i>Quinton</i>
10-18	2 " Frame " <i>Quinton</i>
10/25	3 " Lash End OK <i>Quinton</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>