

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>4330-A</i>	LOCATION <i>3681 East Lincoln Ave.</i>
DATE <i>5/19/36</i>	PURPOSE <i>Erect new residence</i>
ZONE <i>One Fam.</i>	OWNER <i>Mr. & Mrs. Vernon Hansen</i>
	ARCH'T. <i>Holderen Const. Co.</i>
VAL. <i>8000⁰⁰</i>	STORIES <i>2</i>
	ROOMS <i>7</i>
	APTS.
	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS <i>Area 2096⁰</i>
VENT SHAFTS	BOILER ROOMS <i>@ 350</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
9-14-37	1 st Insp. Frame OK <i>Quiter</i>
10-18	2 " Frame " <i>Quiter</i>
10/25	3 " Lash End OK <i>Quiter</i>
COMPLETE AND O. K.	INSPECTOR