

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|----------|------------------------------|-----------------------|---|--|--|-----------------|----------|
| 8-7-70 | Bldg. \$1,200 | G-7863 15.00 | Partns. in basement of com. bldg. | Setro Inc. 5770-Freeport Bl | Brida & Reali .5660-Spilman Av. | Hammons | 12-14-70 |
| 6-9-72 | Bldg \$6,000 | H-7428 36.00 | Int. remodeling | Setro, Inc. | A-1 Const. | Riolo | 8-4-72 |
| 4-25-73 | B-P-E \$4,500. | A-3190 \$46. | Remodl for shoe store & slenderzng clinic | Setro Corp. 5600-Freeport Bl | A-1 Const. 01571 5608-Rickey Dr. | Goodsell | 7-10-73 |
| 4-30-73 | Bldg \$400 | S-7780 \$10. | Const. sign | Setro Corp | Pacific Neon Box 15100, Sacto | Riolo Dikoub | 5-15-73 |
| 4-30-73 | Bldg \$250. | S-7781 \$7.50 | Const. sign | Setro Corp. | Pacific Neon | Trevino | 3-3-80 |
| 4-30-73 | Bldg \$250. | S-7782 \$7.50 | Const. sign | Setro Corp. | Pacific Neon | Trevino | 3-3-80 |
| 3-21-73 | B-E-P-M \$28,000. | A-2008 \$199.50 | Interior remodel Clothing Store | Environmental Mktng, Gr. | Petersen & Assoc. 1800-27th Street | Goodsell | 5-4-73 |
| | | | | | | DiLoretto | 5-10-73 |
| | | | | | | Riolo | 5-15-73 |
| 5-18-73 | Sign \$250.00 | S-7809 \$7.50 | Erect 1 sign | Carlo's Restaurant | Pacific Neon P. O. Box 15100 | Trevino | 3-3-80 |
| 5-18-73 | Sign \$250.00 | S-7810 \$7.50 | Erect 1 sign | Carlo's Restaurant | Same as above | Trevino | 3-3-80 |
| 7-6-73 | Sign \$500.00 | A-7858 \$10 | Sign | Setro Inc | Pacific Neon | Trevino | 3-3-80 |
| 8-9-73 | B-E-P-M \$2,800 | A-6542 \$32. | Remodl portn 1st fl. | Setro Co. 5660- | A-1 Const. Co. | Goodsell | 9-28-73 |
| 3-4-74 | Bldg \$10,000 | B-1271 \$81. | & basmnt in shopng centr/ Const portble roof over opening in mall | Setro Co. 5660-Freeport Blvd. | 5608-Rickey Dr. Lodi Tent & Awning Lodi, CA. | Goodsell | 12-31-73 |
| 3-22-74 | B-E \$8,000 | B-1785 \$67. 7883/ | Install enclosing walls around shopping center | Environmental Marketing Group 5770-Freeport Blvd. | Owner | Riolo | 11-15-74 |
| | | | | | | White | 2-4-76 |
| 5-23-74 | Mech \$250 | B-3656 \$7.50 | Replace gas range | Environmental Marketing Group | Owner | Goodsell | 4-5-74 |
| 11-6-74 | B-E-P-M \$12,000. | B-8760 \$95. | Interior remodel 2nd fl.-restaurant | Environmental Mktg. Group 5770-Freeport Bl. | Owner | Goodsell | 12-5-74 |
| 11-11-74 | B-E-P-M \$300. | B-8863 \$10. | Interior alterations to Shopping Center | Environmental Mktg. Grp. 5770-Freeport | Owner F-2881 | Goodsell | 11-25-74 |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|------------|-------------------------|------------|---------------------|------------|---------------------|
| G-7863 | R287 F24 R350 F160 | S-7810 | R375 F213 | B-8863 | R399 F083 |
| H-7428 | R330 F406-410 R350 F160 | S-7858 | | A-3190 | R335 F201 |
| H-9283 | (Letter) R350 F160 | A-6542 | R360 F24-30 | B-8760 | R335 F202 |
| A-3190 | R 351 F 156-157 | A-6542 | R373 F240-241 | B-3656 | R335 F202 |
| S-7780 | R 351 F 503-504 | A-2008 | | B-8863 | R335 F203 |
| S-7781 | R 351 F 503-504 | B-1271 | R378 F281-284 | B-1785 | R335 F203 |
| S-7782 | R 351 F-503-504 | B-1785 | | A-6542 | R335 F204 |
| A-2008 | R 347 F-440-44 | | R380 F426 | B-1271 | R335 F205 |
| A-2008 | R353 F45 | B-3656 | R385 F91 | 5770-82 | R335 F205 |
| S-7809 | R353 F182 | B-8760 | R398 F568-570 | B-8760 | R448 F206 |

A-3190

S-7780-81-82 R614F582 final

S-7809-10. R614F582

S-7858 R614F582

final

282

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

Card #3

| | | | | | | | | |
|------------------------------------|------------------------|-----------------------|---------------|--------------------------|------------------------|---------------------------------|---------------|------|
| JOB ADDRESS | | 5770 - Freeport Blvd. | | A-3 | | Card #1 and #2 | | |
| SUBDIVISION | | | | REMARKS AND/OR VARIANCES | | in final plan | | |
| LOT NO. | ASSESSORS PARCEL NO. | | | 7-31-74 | | Send notice, cancel permit | | |
| CENSUS TRCT NO. | FIRE ZONE NO. | | | B-11785 | | No inspection Riofo | | |
| OCCUPANCY GROUP | CONSTRUCTION TYPE | | | 8-8-74 | | 1st letter of cancellation sent | | |
| FIRST FL. AREA | TOTAL FLOOR AREA | | | on Permit D-1785 | | GR/nd | | |
| NO. OF ROOMS | NO. OF APARTMENTS | | | 7-31-74 | | Send notice - cancel permit on | | |
| NO. OF STORIES | BUILDING HEIGHT | | | + 8-6542 | | Riofo | | |
| ROOF CONSTR. | EXT. WALL CONSTR. | | | 8-8-74 | | for letter of cancellation sent | | |
| USE ZONE | PARKING SPACES REQD. | | | on Permit A-6542 | | GR/nd | | |
| FIRE SPRKLR. SYS. | FIRE ALARM SYSTEM | | | 8-19-74 | | Send 2nd notice of cancellation | | |
| WET STD. PIPES | DRY STANDPIPES | | | per Riofo on B-11785 | | | | |
| HIRE HYDRANTS | CITY TREES TO BE RMVD. | | | 8-27-74 | | Letter of final expiration | | |
| BUILDING SIZE | WDTH. | FT. X LGTH. | FT= | SQ. FT. | Permit on D-1785 GR/nd | | | |
| SET BACK REQU'M'TS. | LEFT SIDE | FT. RT. SIDE | FT. | | | | | |
| | FRONT | FT. REAR | FT. | | | | | |
| TITLE | NAME | LICENSE NO. | ADDRESS | | | | | |
| OWNER | | | | | | | | |
| GEN. CONTRACTOR | | | | | | | | |
| ARCHITECT | | | | | | | | |
| ENGINEER | | | | | | | | |
| ELECT. CONTR. | | | | | | | | |
| PLUMBING CONTR. | | | | | | | | |
| MECH. CONTR. | | | | | | | | |
| VALUATION | PERMIT FEE:- | PLAN CHECK FEE:- | PENALTY FEE:- | | | | | |
| SEWER INCL. FEE:- | STATE S.M.I. FEE:- | R.D.F. FEE:- | PERMIT NO. | DATE:- | | | | |
| TOTAL FEES: | | | | | | | | |
| FINAL INSPECTIONS | BUILDING BY | DATE | ELECTRICAL BY | DATE | PLUMBING BY | DATE | MECHANICAL BY | DATE |
| CERTIFICATE OF OCCUPANCY ISSUED BY | D. Riofo 3-15-73 | | | A-2008 | | DATE:- | | |
| MICROFILM RECORD | PLANS & APPLICATION | REEL NO:- | FRAME NO:- | TO | JOB FILE REEL NO:- | F. NO | TO | |
| | INSPECTION RECORD | REEL NO:- | FRAME NO:- | TO | | | | |