

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 2159</i>	LOCATION <i>3817 - SAN CARLOS WAY -</i>
DATE <i>12/28/38</i>	PURPOSE <i>Erect new dwlg. 1 gar</i>
ZONE	OWNER <i>Howthey Pierce</i>
	ARCH'T.
	CONTR. <i>H. H. Pierce</i>

VAL. <i>3500.00</i>	STORIES <i>1</i>	ROOMS <i>3</i>	APTS.	SIZE
---------------------	------------------	----------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area 864 sq ft @ 350</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12/30/58	1 ST / NSA Forces OK MW Campbell
	COMPLETE AND O. K. INSPECTOR