

R195 7346-251

| | | | | | |
|-------------------|-----------|--|-----------------|---------------|--------------------------------|
| Lot 21 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$61.00 |
| Parkway Greens #1 | | TYPE BUILDINGS | | | |
| PERMIT NO. | | | | | |
| F-4303 | LOCATION | 79 - Tristan Circle | | | A-5 |
| DATE | PURPOSE | Const. dwlg. & att. gar. | | | |
| May 23-66 | OWNER | Glynn Moore 4900-I Parkway | | | |
| ZONE | ARCH'T | | | | |
| R-1 | CONTR | Owner same GA8-4588 | | | |
| VAL. | \$17,600. | STORIES | ROOMS | APTS. | 407-gar. SIZE 1,777 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 6-2-66 | Barbeto | | | |
| JOIST | 6-13-66 | Barbeto | | | |
| FRAME | 7-19-66 | Chapin | | | |
| SHEET ROCK | 7-31-66 | Chapin | | | |
| FINAL | 9/20/66 | Chapin | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| 7-12-66 | Pt frame - Not used. Chapin |
| 7-18-66 | Pt frame - Stucco were not |
| | Completed OK to SR Chapin |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |