

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| | | | | | | | | | | |
|-----------------------|--------------|-------------------|--------------------|-------------|----------------|---------------|--------------------------|--------------------------|-------------------|------|
| PROPERTY PARCEL NO. | | JOB ADDRESS | | | | | INSPECTION AREA | | FINAL INSPECTIONS | |
| | | 5709 Gilgum Way | | | | | 3-C | | | |
| LEGAL DESCRIPTION | | OCCUP. GR. | CONST TYPE | VAR. NO. | FIRE ZONE | | BUILDING BY | | DATE | |
| Lot 187 C rum Village | | | | | | | Court | | 11/14/57 | |
| TITLE AND NAME | | 1/C | ADDRESS | | ZIP | CITY LIC. NO. | TEL. NO. | | ELECTRICAL BY | DATE |
| GEN. CONTR. | Owner | | 4699-24th St. Road | | | | GL6-8902 | | | |
| ELEC. CONTR. | | | | | | | | | PLUMBING BY | DATE |
| PLBG. CONTR. | | | | | | | | | | |
| MECH. CONTR. | | | | | | | | | MECHANICAL BY | DATE |
| ARCH. ENGR. | | | | | | | | | | |
| OWNER | | E. A. Corum & Son | | | | | | CERTIFICATE OF OCCUPANCY | | |
| CONST. LOAN LENDER | | | | | | | | ISSUED BY | | DATE |
| BLDG. WIDTH | BLDG. LENGTH | TOTAL HEIGHT | NO. OF STORIES | ROOMS | AREA 1st FLOOR | TOTAL AREA | C.S.D. | C.I. CASE | | |
| | | | 1 | 6 | | 1,103 sq. ft. | | CENSUS TRCT. NO. | | |
| SIDE YARDS | REAR YARDS | SET BACK REQ. | USE ZONE | PARK'G REQ. | SPACES | TREES RMVD. | EXISTING BLDG'S SAME LOT | | HOW USED | |
| | | | | | | | | | | |

NATURE OF WORK:- Const. dwelling & garage

| | | | | | |
|-----------------|-------------|--------------------------|-------------|----------------|--------|
| PERMIT NO. S.P. | C-6983 | MICROFILM RECORD | | | |
| ISSUED BY | | | | | |
| ISSUANCE DATE | 7/23/57 | PLANS AND APPLICATION | REEL NO. 35 | FRAME NO:- 583 | TO 684 |
| VALUATION | \$10,300.00 | INSPECTION RECORD | REEL NO. | FRAME NO:- | TO |
| R.D.F. FEE | \$ | JOB FILE | REEL NO. | FRAME NO:- | TO |
| S.M.I. FEE | \$ | | | | |
| PLAN CK. FEE | \$ | | | | |
| SEWER INCL. FEE | \$ | | | | |
| PERMIT FEE | \$ 31.00 | REMARKS AND/OR VARIANCES | | | |
| | \$ | DWELLING | | | |
| | \$ | | | | |
| TOTAL FEES | \$ | | | | |

3507P082 - final

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|---------|------------------------------|--------------------|---|-------------------------------|-------------------------------------|--------------------|----------|
| 6/27/77 | B.P. \$ 1500.00 | E-4745 \$ 40.00 | water damage shower repair | Richard Gong Same | Crawford, Pomeroy & Wilson Const | <i>[Signature]</i> | 7/8/77 |
| 5/24/63 | Bldg. \$1,500.00 | E-3989 \$13.00 | Enlarge Roomkadd 2nd bath to dwlg./132 sq.ft. | Richard Gong Same/GAL-0521 | W.W. Gordon 5709-Monterey Way | Larsen | 10/30/63 |
| 7-16-81 | B \$490. | I-3395 \$20. | Play ramp/wheel chair | Larry Gong 5709 Gilgum Way | Erik Antonez 4605 North Ave. | <i>[Signature]</i> | 7/28/81 |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|------------|---------------------|------------|---------------------|------------|---------------------|
| E-4745 | 486R026 | E-3989 | 1490R517 | E-3989 | 1490R517 |
| E-4745 | 1490R517 | E-3989 | 1490R517 | E-3989 | 1490R517 |
| E-3989 | 1490R517 | E-3989 | 1490R517 | E-3989 | 1490R517 |
| E-3989 | 1490R517 | E-3989 | 1490R517 | E-3989 | 1490R517 |
| I-3395 | 6078R147-148 | I-3395 | 6078R147-148 | I-3395 | 6078R147-148 |
| I-3395 | 6078R147-148 | I-3395 | 6078R147-148 | I-3395 | 6078R147-148 |
| I-3395 | 6078R147-148 | I-3395 | 6078R147-148 | I-3395 | 6078R147-148 |
| I-3395 | 6078R147-148 | I-3395 | 6078R147-148 | I-3395 | 6078R147-148 |

[Handwritten notes and signatures]
 E-3989
 R X 1 F 260
 I-3395
 6078R147-148
 486R026
 1490R517
 1490R517
 1490R517