

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-3388</i>	LOCATION <i>1940-Vallejo Way</i>			
DATE <i>7/6/39</i>	PURPOSE <i>New dwlg.</i>			
ZONE	OWNER <i>Walter Sanders</i>			
	ARCH'T. <i>Chas McCuire</i>			
	CONTR.			
VAL. <i>4900<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1330<sup>00</sup></i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
7/8/39	1 <sup>ST</sup> N.S.P. Forms in place OF A. W. Campbell
7/27/39	2 <sup>ND</sup> N.S.P. Forms . . . . . OR A. W. Campbell
	<p data-bbox="254 865 378 906">COMPLETE AND O. K.</p> <p data-bbox="1049 880 1185 906">INSPECTOR</p>