

*B-318F150-*

<b>Lot 249</b>		<b>BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD</b>			<b>\$78.00</b>
<b>Southfield Estates Unit #2 TYPE BUILDINGS</b>					
<b>PERMIT NO.</b>					
<b>H-4880</b>		<b>LOCATION 7484 - Poirier Way A-5 (42)</b>			
<b>DATE</b>		<b>PURPOSE</b>			
<b>Dec. 21-71</b>		<b>Const. dwelling &amp; att. garage MP 1300</b>			
		<b>OWNER</b>			
		<b>Geo. Brandon 2454-Loma Vista Drive</b>			
<b>ZONE</b>		<b>ARCH'T</b>			
<b>R-1</b>					
		<b>CONTR</b>			
		<b>Brandon Const. Same 481 3920</b>			
<b>VAL \$18,200.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
		<b>1</b>			<b>475-gar. 1,300 sq. ft.</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>	<i>1-7-72</i>	<i>Brick</i>			
<b>JOIST</b>	<i>1-21-72</i>	<i>Block</i>			
<b>FRAME</b>	<i>2-17-72</i>	<i>Brick</i>			
<b>SHEET ROCK</b>	<i>3-6-72</i>	<i>Brick</i>			
<b>FINAL</b>	<i>4-25-72</i>	<i>Perk</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
1-19-72	Pl. Grout - Plumbing details <sup>not</sup> filled
1-20-72	Pl. Joint - plugging w/ board & ditches
2-29-72	Back filled - 1st. fl. not ready      2nd fl.      3rd fl.
4-18-72	Pl. Locked      4th fl.
4-19-72	Pl. Final - Locked up      5th fl.
COMPLETE AND OK	INSPECTOR