

| | | | | | |
|----------------|----------------|---|-----------------|---------------|---------|
| Lot 289 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$46.00 |
| Glenbrook #3 | | TYPE BUILDINGS <i>R180 2480-489</i> <i>R191 7388</i> | | | |
| PERMIT NO. | | | | | |
| F-3720 | LOCATION | 8572 - Merribrook Drive | | | A-1 |
| DATE | PURPOSE | Const. dwelling & gar. Plan 401 E | | | |
| Apr. 6-66 | OWNER | Center Dev., Inc. 2777-Alvarado St. | | | |
| ZONE | ARCH'T | | | | |
| R-1 | CONTR | Besco | Same | 363-7315 | |
| VAL. \$12,400. | STORIES | ROOMS | APTS. | 494-gar. SIZE | |
| | 1 | 5 | | 1,232 sq.ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | <i>4.8.66</i> | <i>Hammock</i> | | | |
| JOIST | <i>4.20.66</i> | <i>Conest</i> | | | |
| FRAME | <i>5.18.66</i> | <i>Larsen</i> | | | |
| SHEET ROCK | <i>5.24.66</i> | <i>Hammock</i> | | | |
| FINAL | <i>7.8.66</i> | <i>E Larsen</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|---|
| 4-19-66 | PH Crick's job ready <i>W. J. [unclear]</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |