

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,387</i>	LOCATION <i>116 - Tricoli Way.</i>			
DATE <i>5/22/42</i>	PURPOSE <i>Erect new dwg. & gar.</i>			
ZONE	OWNER <i>Mary E. Phillips</i>			
	ARCH'T. <i>W. B. Phillips</i>			
	CONTR. <i>W. B. Phillips</i>			
VAL. <i>3000⁰⁰</i>	STORIES <i>2</i>	ROOMS <i>4</i>	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS		<i>area</i>	
VENT SHAFTS	BOILER ROOMS		<i>78 sq ft.</i>	
OWNER'S INSPECTOR	SPRINKLER SYSTEM		<i>@ 350</i>	
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK-REMARKS
1917	Jasp Form O.K.
5/13/17	" " Form O.K.
	<p data-bbox="289 844 422 890">COMPLETE AND O. K.</p> <p data-bbox="1090 859 1224 885">INSPECTOR</p>